



**LH-SI-01 ACCESSIBLE PARKING STALL ADDITION**

An additional parking stall is needed for disabled individuals and to meet ADA requirements.



**LH-SI-10 CURB RAMP ADDITION**

A curb ramp is needed at the front entry for wheelchair access and to meet ADA requirements.



**LH-SI-20 PLAYGROUND MARKING UPGRADE**

New pavement markings needed for playground game lines.



**LH-ST-07 MECHANICAL EQUIPMENT ANCHORING**

Mechanical equipment needs to be anchored in place for seismic support.



**LH-ST-09 MASONRY WALL CRACK REPAIR**

Masonry repair needed at cracks in exterior walls to protect walls from water infiltration and structural damage.



**LH-ST-11 BEAM DRY ROT REPAIR**

Repair of dry rot at exterior wood beams needed to protect against further damage and deterioration.



**LH-ST-12 BRICK REPLACEMENT**

Repair of brick at exterior masonry wall at 400 Unit needed to protect wall from water infiltration and structural damage.



**LH-ST-13 MORTAR JOINT REPAIR**

Masonry repair needed at mortar joints at Gym to protect walls from water infiltration and structural damage.



**LH-EQ-01 COMPUTER FURNITURE UPGRADE**

Computer furniture needed to properly accommodate students and computer equipment.