



Name of Sampler: Lisa Christensen
Date Collected: 06/06/2019
School Name: Alpac Elementary
School Code: 3825
School District: Auburn
School Address: 310 Milwaukee Blvd North, Pacific WA 98047
School County: King
Number of Samples Collected: 58
School Point of Contact (POC): Randy Thomas
POC Title: Director of Maintenance and Operations
POC Email: RThomas@auburn.wednet.edu
POC Phone Number: (253) 931-4955
Date Samples Sent to Lab: 06/06/2019
Date Samples Received by Lab: 06/27/2019
Shipment Tracking Number: NA

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25069	other	other		<1	07/02/2019	7:37 AM, 06694
25070	FirstDraw	Bubbler	Outside Kitchen	3	07/02/2019	
25108	FirstDraw	other	Kitchen, Food Prep Area	2	07/02/2019	Near 2-Sink compartment
25109	FirstDraw	Tap	Kitchen, Food Prep Area	13	07/02/2019	Across from Sprayer
25110	FirstDraw	Tap	Nurses Room	1	07/02/2019	
25111	FirstDraw	Bubbler	Room 107	5	07/02/2019	
25112	FirstDraw	Tap	Room 107	2	07/02/2019	
25113	FirstDraw	Bubbler	Room 109	1	07/02/2019	
25114	FirstDraw	Tap	Room 109	2	07/02/2019	
25115	FirstDraw	Bubbler	Across from Gym	<1	07/02/2019	
25116	FirstDraw	BottleFiller	Across from Gym	<1	07/02/2019	
25117	FirstDraw	Bubbler	Room 201	5	07/02/2019	
25118	FirstDraw	Tap	Room 201	6	07/02/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25119	FirstDraw	Bubbler	Room 211	4	07/02/2019	
25120	FirstDraw	Tap	Room 211	2	07/02/2019	
25121	FirstDraw	Bubbler	Room 212	9	07/02/2019	Mineral deposits on bubbler
25122	FirstDraw	Tap	Room 212	22	07/02/2019	
25123	FirstDraw	Bubbler	Room 210	7	07/02/2019	Some mineral deposits on bubbler
25124	FirstDraw	Tap	Room 210	25	07/02/2019	Some mineral deposits In aerator
25125	FirstDraw	Bubbler	Room 207	<1	07/02/2019	Corrosion on bubbler
25126	FirstDraw	Tap	Room 207	9	07/02/2019	
25127	FirstDraw	Bubbler	Room 206	<1	07/02/2019	Small amount of corrosion on bubbler
25128	FirstDraw	Tap	Room 206	16	07/02/2019	
25129	FirstDraw	Bubbler	Room 205	2	07/02/2019	Some mineral deposits on bubbler
25130	FirstDraw	Tap	Room 205	6	07/02/2019	
25131	Flush	Bubbler	Room 203	2	07/02/2019	
25132	FirstDraw	Tap	Room 203	6	07/02/2019	
25133	FirstDraw	Tap	Library Workroom	74	07/19/2019	
25134	FirstDraw	Bubbler	Room 307	4	07/02/2019	
25135	FirstDraw	Tap	Room 307	16	07/02/2019	
25136	FirstDraw	Bubbler	Room 306	6	07/02/2019	
25137	FirstDraw	Tap	Room 306	31	07/02/2019	
25138	FirstDraw	Bubbler	Room 304	1	07/02/2019	
25139	FirstDraw	Tap	Room 304	4	07/02/2019	
25140	FirstDraw	Bubbler	Room 303	2	07/02/2019	
25141	FirstDraw	Tap	Room 303	3	07/02/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25142	FirstDraw	Bubbler	Room 302	1	07/02/2019	
25143	FirstDraw	Tap	Room 302	13	07/02/2019	
25144	FirstDraw	Bubbler	Room 301	4	07/02/2019	
25145	FirstDraw	Tap	Room 301	17	07/02/2019	
25146	FirstDraw	Bubbler	Near 401 and 402 (Near Bathrooms)	<1	07/02/2019	
25147	FirstDraw	BottleFiller	Near 401 and 402 (Near Bathrooms)	<1	07/02/2019	
25148	FirstDraw	Bubbler	Room 406	4	07/02/2019	
25149	FirstDraw	Tap	Room 406	11	07/02/2019	
25150	FirstDraw	Bubbler	Room 408	2	07/02/2019	
25151	FirstDraw	Tap	Room 408	9	07/02/2019	
25152	FirstDraw	Bubbler	Room 410	5	07/02/2019	
25153	FirstDraw	Tap	Room 410	8	07/02/2019	
25154	FirstDraw	Bubbler	Room 412	4	07/02/2019	
25155	FirstDraw	Tap	Room 412	11	07/02/2019	
25156	FirstDraw	Bubbler	Room 409	3	07/02/2019	Mineral deposits and corrosion
25157	FirstDraw	Tap	Room 409	12	07/02/2019	
25158	FirstDraw	Bubbler	Room 411	3	07/02/2019	Corrosion and lots of mineral deposits
25159	FirstDraw	Tap	Room 411	14	07/02/2019	Used this morning
25160	FirstDraw	Bubbler	Room 407	7	07/02/2019	
25161	FirstDraw	Tap	Room 407	23	07/02/2019	
25162	FirstDraw	Bubbler	Room 405	11	07/02/2019	
25163	FirstDraw	Tap	Room 405	27	07/02/2019	