



Name of Sampler: Lisa Christensen
Date Collected: 06/07/2019
School Name: Arthur Jacobsen Elementary
School Code: 5082
School District: Auburn
School Address: 29205 132nd Ave Southeast, Auburn WA 98092
School County: King
Number of Samples Collected: 72
School Point of Contact (POC): Randy Thomas
POC Title: Director of Maintenance and Facilities
POC Email: RThomas@auburn.wednet.edu
POC Phone Number: (253) 931-4955
Date Samples Sent to Lab: 06/07/2019
Date Samples Received by Lab: 06/28/2019
Shipment Tracking Number: NA

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25164	other	other		<1	07/03/2019	06737, 6:37 AM
25165	FirstDraw	Tap	Health Room	<1	07/03/2019	
25166	FirstDraw	Bubbler	Room 107	<1	07/03/2019	Left Sink
25167	FirstDraw	Tap	Room 107	<1	07/03/2019	Left Sink
25168	FirstDraw	Bubbler	Room 107	<1	07/03/2019	Right Sink
25169	FirstDraw	Tap	Room 107	<1	07/03/2019	Right Sink
25170	FirstDraw	Bubbler	Room 109	<1	07/03/2019	Left Sink, Small amount of black slime on bubbler
25171	FirstDraw	Tap	Room 109	<1	07/03/2019	Left Sink, No aerator
25172	FirstDraw	Bubbler	Room 109	<1	07/03/2019	Right Sink, Some mineral depositson bubbler
25173	FirstDraw	Tap	Room 109	<1	07/03/2019	Right Sink
25174	FirstDraw	Bubbler	Outside Gym	<1	07/03/2019	Left

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25175	FirstDraw	Bubbler	Outside Gym	<1	07/03/2019	Right
25176	FirstDraw	Tap	Room 112 B in Library	3	07/03/2019	
25177	FirstDraw	Tap	Room 117	<1	07/03/2019	Music Room
25178	FirstDraw	Tap	Room 118	<1	07/03/2019	Mineral deposits in aerator
25179	FirstDraw	Tap	Kitchen, 2-Sink compartment near back	<1	07/03/2019	Left Tap, Used this morning
25180	FirstDraw	Tap	Kitchen, 2-Sink compartment near back	<1	07/03/2019	Right Tap
25181	FirstDraw	Bubbler	Outside Maintenance Office (Room 123)	<1	07/03/2019	Left
25182	FirstDraw	Bubbler	Outside Maintenance Office (Room 123)	<1	07/03/2019	Right
25183	FirstDraw	Bubbler	Room 135	<1	07/03/2019	
25184	FirstDraw	Tap	Room 135	<1	07/03/2019	
25185	FirstDraw	Bubbler	Room 137	<1	07/03/2019	Some mineral deposits on bubbler
25186	FirstDraw	Tap	Room 137	<1	07/03/2019	
25187	FirstDraw	Bubbler	Room 139	<1	07/03/2019	
25188	FirstDraw	Tap	Room 139	<1	07/03/2019	
25189	FirstDraw	Bubbler	Room 141	<1	07/03/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25190	FirstDraw	Tap	Room 141	<1	07/03/2019	
25191	FirstDraw	Bubbler	Next to Room 145	<1	07/03/2019	Left
25192	FirstDraw	Bubbler	Next to Room 145	<1	07/03/2019	Right
25193	FirstDraw	Bubbler	Room 145	<1	07/03/2019	
25194	FirstDraw	Tap	Room 145	<1	07/03/2019	
25195	FirstDraw	Bubbler	Room 146	<1	07/03/2019	
25196	FirstDraw	Tap	Room 146	<1	07/03/2019	
25197	FirstDraw	other	Portable 2 (Room 902)	<1	07/03/2019	
25198	FirstDraw	Bubbler	Room 144	<1	07/03/2019	Some mineral deposits on bubbler
25199	FirstDraw	Tap	Room 144	<1	07/03/2019	
25200	FirstDraw	Bubbler	Room 138	<1	07/03/2019	
25201	FirstDraw	Tap	Room 138	<1	07/03/2019	Tap Drips
25202	FirstDraw	Bubbler	Room 136	<1	07/03/2019	
25203	FirstDraw	Tap	Room 136	<1	07/03/2019	
25204	FirstDraw	Bubbler	Room 134	<1	07/03/2019	Mineral deposits on bubbler
25205	FirstDraw	Tap	Room 134	<1	07/03/2019	Mineral deposits and rust on aerator
25206	FirstDraw	Bubbler	Room 132	<1	07/03/2019	
25207	FirstDraw	Tap	Room 132	1	07/03/2019	
25208	FirstDraw	Bubbler	Near 2nd Floor Elevators	<1	07/03/2019	Left
25209	FirstDraw	Bubbler	Near 2nd Floor Elevators	<1	07/03/2019	Right
25210	FirstDraw	Bubbler	Room 205	<1	07/03/2019	Mineral deposits on bubbler
25211	FirstDraw	Tap	Room 205	3	07/03/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25212	FirstDraw	Bubbler	Room 207	<1	07/03/2019	
25213	FirstDraw	Tap	Room 207	<1	07/03/2019	Mineral deposits in and around aerator
25214	FirstDraw	Bubbler	Room 209	<1	07/03/2019	
25215	FirstDraw	Tap	Room 209	<1	07/03/2019	
25216	FirstDraw	Bubbler	Room 211	<1	07/03/2019	Mineral deposits on bubbler
25217	FirstDraw	Tap	Room 211	<1	07/03/2019	
25218	FirstDraw	Bubbler	Room 213	<1	07/03/2019	
25219	FirstDraw	Tap	Room 213	<1	07/03/2019	
25220	FirstDraw	Bubbler	Near Room 217 (End of Hallway on 2nd Floor)	<1	07/03/2019	Left
25221	FirstDraw	Bubbler	Near Room 217 (End of Hallway on 2nd Floor)	<1	07/03/2019	Right
25222	FirstDraw	Bubbler	Room 217	<1	07/03/2019	Mineral deposits on bubbler
25223	FirstDraw	Tap	Room 217	<1	07/03/2019	
25224	FirstDraw	Bubbler	Room 218	<1	07/03/2019	
25225	FirstDraw	Tap	Room 218	1	07/03/2019	
25226	FirstDraw	Bubbler	Room 216	<1	07/03/2019	
25227	FirstDraw	Tap	Room 216	<1	07/03/2019	
25228	FirstDraw	Bubbler	Room 212	<1	07/03/2019	
25229	FirstDraw	Tap	Room 212	<1	07/03/2019	
25230	FirstDraw	Bubbler	Room 210	<1	07/03/2019	
25231	FirstDraw	Tap	Room 210	<1	07/03/2019	
25232	FirstDraw	Bubbler	Room 208	<1	07/03/2019	
25233	FirstDraw	Tap	Room 208	<1	07/03/2019	
25234	FirstDraw	Bubbler	Room 206	<1	07/03/2019	
25235	FirstDraw	Tap	Room 206	<1	07/03/2019	