



**PI-SI-08 CURB RAMP ADDITION**

Curb ramp needed at front of school to provide wheelchair access and to meet ADA requirements.



**PI-SI-16 PAVEMENT MARKING UPGRADE**

Thermo-plastic pavement markings needed for traffic control and painted game lines needed at playground.



**PI-IN-09 INTERIOR DOOR HARDWARE UPGRADE**

Lever handles needed at interior doors to improve access for disabled individuals and to meet ADA requirements.



**PI-ST-08 BEAM DRY ROT REPAIR**

Repair of dry rot at exterior wood beams needed to protect against further damage and deterioration.



**PI-ST-09 MECHANICAL EQUIPMENT ANCHORING**

Mechanical equipment needs to be anchored in place for seismic support.



**PI-ST-12 MORTAR JOINT REPAIR**

Masonry repair needed at mortar joints to protect walls from water infiltration and structural damage.



**PI-EQ-01      COMPUTER FURNITURE UPGRADE**

Computer furniture needed to properly accommodate students and computer equipment.