



Name of Sampler: Lisa Christensen
Date Collected: 06/11/2019
School Name: Hazelwood Elementary
School Code: 4347
School District: Auburn
School Address: 11815 Southeast 304th St, Auburn WA 98092
School County: King
Number of Samples Collected: 61
School Point of Contact (POC): Randy Thomas
POC Title: Director of Maintenance and Facilities
POC Email: RThomas@auburn.wednet.edu
POC Phone Number: (253) 931-4955
Date Samples Sent to Lab: 06/11/2019
Date Samples Received by Lab: 07/05/2019
Shipment Tracking Number: NA

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25236	other	other		<1	07/10/2019	06678, 6:37 AM
25237	FirstDraw	Tap	Health Room	<1	07/10/2019	
25238	FirstDraw	Bubbler	Room 106	<1	07/10/2019	Lots of mineral deposits on spout
25239	FirstDraw	Tap	Room 106	1	07/10/2019	
25240	FirstDraw	Bubbler	Room 107	1	07/10/2019	Mineral deposits on spout
25241	FirstDraw	Tap	Room 107	3	07/10/2019	
25242	FirstDraw	Bubbler	Outside Gym	<1	07/10/2019	
25243	FirstDraw	BottleFiller	Outside Gym	<1	07/10/2019	
25244	FirstDraw	Tap	Kitchen (Back Wall Sink on Left)	<1	07/10/2019	Used this morning
25245	FirstDraw	other	Kitchen Back Wall Sink on Left	<1	07/10/2019	Used this morning

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25246	FirstDraw	Tap	Room 113, Kitchenette	4	07/10/2019	
25247	FirstDraw	Bubbler	Room 124	5	07/10/2019	
25248	FirstDraw	Tap	Room 124	3	07/10/2019	
25249	FirstDraw	Tap	Kitchen	2	07/10/2019	Metal taper on tap with some mineral deposit accumulation
25250	FirstDraw	Bubbler	Room 130	27	07/10/2019	
25251	FirstDraw	Tap	Room 130	1	07/10/2019	
25252	FirstDraw	Tap	Room 131	4	07/10/2019	No Aerator
25253	FirstDraw	Bubbler	Room 203	1	07/10/2019	
25254	FirstDraw	Tap	Room 203	1	07/10/2019	
25255	FirstDraw	Bubbler	Room 204	<1	07/10/2019	
25256	FirstDraw	Tap	Room 204	1	07/10/2019	
25257	FirstDraw	Bubbler	Room 206	3	07/10/2019	
25258	FirstDraw	Tap	Room 206	1	07/10/2019	
25259	FirstDraw	Bubbler	Room 207	2	07/10/2019	
25260	FirstDraw	Tap	Room 207	1	07/10/2019	
25261	FirstDraw	Bubbler	Room 205	<1	07/10/2019	
25262	FirstDraw	Tap	Room 205	1	07/10/2019	
25263	FirstDraw	Bubbler	Room 202	1	07/10/2019	
25264	FirstDraw	Tap	Room 202	1	07/10/2019	
25265	FirstDraw	Bubbler	Room 201	1	07/10/2019	
25266	FirstDraw	Tap	Room 201	1	07/10/2019	
25267	FirstDraw	Bubbler	Room 303	1	07/10/2019	
25268	FirstDraw	Tap	Room 303	2	07/10/2019	
25269	FirstDraw	Bubbler	Room 306	1	07/10/2019	
25270	FirstDraw	Tap	Room 306	3	07/10/2019	
25271	FirstDraw	Bubbler	Room 307	2	07/10/2019	
25272	FirstDraw	Tap	Room 307	3	07/10/2019	
25273	FirstDraw	Bubbler	Room 310	1	07/10/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25274	FirstDraw	Tap	Room 310	1	07/10/2019	Lots of mineral deposit on spout and part of spout missing
25275	FirstDraw	Bubbler	Room 311	<1	07/10/2019	
25276	FirstDraw	Tap	Room 311	3	07/10/2019	
25277	FirstDraw	Bubbler	Room 305	<1	07/10/2019	
25278	FirstDraw	Tap	Room 305	1	07/10/2019	
25279	FirstDraw	Bubbler	Room 304	<1	07/10/2019	
25280	FirstDraw	Tap	Room 304	2	07/10/2019	
25281	FirstDraw	Bubbler	Room 301	8	07/10/2019	
25282	FirstDraw	Tap	Room 301	1	07/10/2019	
25283	FirstDraw	Bubbler	Room 401	2	07/10/2019	
25284	FirstDraw	Tap	Room 401	4	07/10/2019	
25285	FirstDraw	Bubbler	Room 403	<1	07/10/2019	
25286	FirstDraw	Tap	Room 403	1	07/10/2019	Tap Drips
25287	FirstDraw	Bubbler	Room 405	1	07/10/2019	
25288	FirstDraw	Tap	Room 405	2	07/10/2019	
25289	FirstDraw	Bubbler	Room 410	<1	07/10/2019	Some mineral deposits on bubbler
25290	FirstDraw	Tap	Room 410	2	07/10/2019	
25291	FirstDraw	Bubbler	Room 409	1	07/10/2019	
25292	FirstDraw	Tap	Room 409	2	07/10/2019	
25293	FirstDraw	Bubbler	Room 406	1	07/10/2019	Mineral deposits on bubbler
25294	FirstDraw	Tap	Room 406	3	07/10/2019	
25295	FirstDraw	Bubbler	Room 404	1	07/10/2019	
25296	FirstDraw	Tap	Room 404	4	07/10/2019	